

1/2024-25

FITNESS CERTIFICATE

To be filed by the Inspecting Officer (Asst. Engineer)
(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer : Aswini.T
2. Name of the School : Hill View International School
3. Location with name of Education District / Sub.District : Koodathai Bazar
: Thamarassery Education District
4. Classification of Building as specified in column 4 of the Application for fitness certificate and size : RCC framed structure
5 (6.90*6.90*3.75 m) GF (Circular Rooms)
2 (7.00*5.80*3.75 m) GF (Semi Elliptical Rooms)
5 (6.90*6.90*3.75 m) FF (Circular Rooms)
2 (7.00*5.80*3.75 m) FF (Semi Elliptical Rooms)

Permenant multi storied Building
5. Period for which the certificate is issued : 2024-25
6. Nature of defects,if and
 - a) Foundation and basement : Nil
 - b) Super structure : Nil
 - c) Doors and Windows : Nil
 - d) Wood work wrought and put up : Nil
 - e) Roof : Nil
 - f) Flooring : Nil
 - g) Miscellaneous (Cracks,etc.) : Nil
7. Any major defects noticed which will render the Building unsafe in any manner : No
8. Whether maintenance works have been one properly : Yes
9. Whether the structure is sound or not for conducting classes : Sound under normal weather and wind conditions

Note :1. The stability of the structure should be examined also with reference to location altitude, intensity of wind, exposure of flood etc.
2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

Certified that the school building was inspected by me on 06.04.2024 and found to be fit to conduct classes for the period 2024-25 for the reasons stated above.

Place : Omassery

Date: 08.04.2024

(Seal)



Aswini
Assistant Engineer
**ASSISTANT ENGINEER
LID & EW
SECTION OMASSERY**